











LLOYD, TRAVIS	142 NIEHOFF DR	142 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
VOSBERG, HEATHER	153 NIEHOFF DR	153 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
EBERT, MICHAEL J	154 NIEHOFF DR	154 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
WHITE, JOHN	165 NIEHOFF DR	165 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
DIAZ, FERNANDO & MARIA	166 NIEHOFF DR	166 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
PEARSON, TWILA	203 NIEHOFF DR	203 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
STRELOW, BRYON	216 NIEHOFF DR	216 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
FISHER, KYLE	218 NIEHOFF DR	218 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
TAYLOR, SHAWNA	226 NIEHOFF DR	226 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
GARRISON, JOE	227 NIEHOFF DR	227 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
MOJINEY, JOSHUA	228 NIEHOFF DR	228 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
CZARNEKI, TONYA	238 NIEHOFF DR	238 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
FISCHER, PAUL & THERESA	240 NIEHOFF DR	240 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
PELLETT, DANIEL	243 NIEHOFF DR	243 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
MARTINSON, CHRIS	248 NIEHOFF DR	248 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
ROHRBECK, DAWN	250 NIEHOFF DR	250 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
SKILTON, LINDA	251 NIEHOFF DR	251 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
ALLEN, CHRISTINE & KENNETH	259 NIEHOFF DR	259 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
GOULD, MAX	262 NIEHOFF DR	262 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
SCHNURR, MATTHEW & KATHRYN	267 NIEHOFF DR	267 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
SANFORD, CLARENCE	268 NIEHOFF DR	268 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
RUPPEL, JENNY	274 NIEHOFF DR	274 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
HANSON, KEITH & SHARON	275 NIEHOFF DR	275 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
WOUDSTRA, JAMES	280 NIEHOFF DR	280 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
SULLIVAN, JUDY	283 NIEHOFF DR	283 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
HURST, JEFFREY	286 NIEHOFF DR	286 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
GROSSMAN, KEITH & BEV	291 NIEHOFF DR	291 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
GOULD, MARK	292 NIEHOFF DR	292 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
CHASE, BRIAN	298 NIEHOFF DR	298 NIEHOFF DR	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
SAVANNA OAKS CULTURAL CENTER	100 POSER RD	100 POSER RD	N	DI	N	1"	C	NONRES	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
ARNOLD, JESSE	109 PRAIRIE ST	109 PRAIRIE ST	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
KOEHLER, KATHY	114 PRAIRIE ST	114 PRAIRIE ST	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
LARSON, DIANE	175 PRAIRIE ST	175 PRAIRIE ST	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
WAGNER, BILLIE	212 PRAIRIE ST	212 PRAIRIE ST	N	C	N	1"	C	SF	Installed after lead ba	Y	Visual insp during Installed after lead ban	N	
SACQUITTE, ANDREW	301 PRAIRIE ST	301 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
MORSCHAUSER, PAUL	307 PRAIRIE ST	307 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
FALL RIVER SCHOOL SPORTS COMP	310 PRAIRIE ST	310 PRAIRIE ST	N	C	N	1"	2020	C	SCH/DC	Installation record	Y	2018	Visual insp during install or repair
SWENO, DUWAYNE	313 PRAIRIE ST	313 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
GREILING, AARON	319 PRAIRIE ST	319 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
LISKA, FRANK & PEGGY	325 PRAIRIE ST	325 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
DAUMAN, JORDAN & HANNAH	331 PRAIRIE ST	331 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
VAN GYSEL, BRENT	337 PRAIRIE ST	337 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
GREEN, KARI	343 PRAIRIE ST	343 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
CURKETT, CODY & ALYSSA	349 PRAIRIE ST	349 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
KUEHL, JESSE & DORI	355 PRAIRIE ST	355 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
DOWDELL, SPENCER	361 PRAIRIE ST	361 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair
FALL RIVER EXPRESS	143 QUALITY CT	143 QUALITY CT	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair
BADGER EXPRESS	161 QUALITY CT	161 QUALITY CT	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair
BADGER EXPRESS	181 QUALITY CT	181 QUALITY CT	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair
METALCRAFT OF MAYVILLE INC	400 QUALITY CT	400 QUALITY CT	N	DI	N	6"	2004	DI	NONRES	Installation record	Y	2004	Visual insp during install or repair
BADGER CUSTOM PALLET LLC	450 QUALITY CT	450 QUALITY CT	N	DI	N	6"	2004	DI	NONRES	Installation record	Y	2004	Visual insp during install or repair
BADGER CUSTOM PALLET LLC	460 QUALITY CT	460 QUALITY CT	N	DI	N	6"	2004	DI	NONRES	Installation record	Y	2004	Visual insp during install or repair
CALAMARI TRUST	112 S MAIN ST	112 S MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
RABL, KAYLEN	120 S MAIN ST	120 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
ROBBINS, KYLE	129 S MAIN ST	129 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
FICHTINGER, PAUL	133 S MAIN ST	133 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
BERNDT, SEAN	134 S MAIN ST	134 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
BUCHDA, MADELYN	138 S MAIN ST	138 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
HANOUSEK, MICHAEL	142 S MAIN ST	142 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
PETRIE, TIMOTHY	143 S MAIN ST	143 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
ADEGLEEN, BRIAN	148 S MAIN ST	148 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
LEPKE, KAITLYN	149 S MAIN ST	149 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
MUHLENBECK, NICOLE	153 S MAIN ST	153 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
DEGROOT, ROBERT & MARK	156 S MAIN ST	156 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
GEHRKE, PHIL	167 S MAIN ST	167 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
MCDONALD, RUTH	203 S MAIN ST	203 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
JAYNES, TIM	206 S MAIN ST	206 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
LANGTON, WILBERT	207 S MAIN ST	207 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
RENTMEISTER, TIMOTHY	211 S MAIN ST	211 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
HUGGETT, TODD	216 S MAIN ST	216 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
DKYKSTRA, JOYCE	217 S MAIN ST	217 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
ZINDA, DALE	224 S MAIN ST	224 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
EWING, BANKRUPTCY	230 S MAIN ST	230 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
OELKE, GARY	231 S MAIN ST	231 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
HUGHES, ROBERT	235 S MAIN ST	235 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
MILLIUS, MURIEL	236 S MAIN ST	236 S MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
BROCK, HUNTER	238 S MAIN ST	238 S MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
SWISSDORF, JOEL & KIM	243 S MAIN ST	243 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
LYNN PROPERTIES LLC	244 S MAIN ST	244 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
LOHAUS, ANGELA	249 S MAIN ST	249 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
VANDERWERFF, JOHN	252 S MAIN ST	252 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
FLEISCHER, CHRISTY	302 S MAIN ST	302 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
RIVERS, TIM & ERICA	305 S MAIN ST	305 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
MAENNER, CHARLES & ANNA	308 S MAIN ST	308 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
GILLETT, KENNETH	314 S MAIN ST	314 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
HILLIARD, AMY	317 S MAIN ST	317 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
HAZARD, BENJAMIN & PAULA	320 S MAIN ST	320 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
HUBER, TIM	326 S MAIN ST	326 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only
BAASKE, TERRY	329 S MAIN ST	329 S MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace recv	Y	2003	Visual insp during Field inspection only



TRAMBURG, BRYAN	316 SOUTH ST	316 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
SCHULTZ, DAVID & ANGELICA	321 SOUTH ST	321 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
DYKSTRA, RICHARD	322 SOUTH ST	322 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
DYKSTRA, KERIA	325 SOUTH ST	325 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
SCHULTZ, CRAIG	333 SOUTH ST	333 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
LEISMANN, EUGENE	334 SOUTH ST	334 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
WEISENSEL, JULIUS & MEGAN	341 SOUTH ST	341 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
NELSON, DANIELLE	346 SOUTH ST	346 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
BERNDT, RUSSELL	357 SOUTH ST	357 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace rec	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
DYKSTRA, MARK	386 SOUTH ST	386 SOUTH ST	N	C	N	1"	2001	C	SF	Installation record	Y	2001	Visual insp during Installation record	Y		
DYKSTRA, MIKE	394 SOUTH ST	394 SOUTH ST	N	C	N	1"	2001	C	SF	Installation record	Y	2001	Visual insp during Installation record	Y		
DYKSTRA, RENEE	396 SOUTH ST	396 SOUTH ST	N	C	N	1"	2001	C	SF	Installation record	Y	2001	Visual insp during Installation record	Y		
BROWN, JOHN & MADOLYN	398 SOUTH ST	398 SOUTH ST	N	C	N	1"	2017	C	SF	Installation record	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
GUMZ, CODY	400 SOUTH ST	400 SOUTH ST	N	C	N	1"	2017	C	SF	Installation record	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
KURLINSKI, JOANNE	411 SOUTH ST	411 SOUTH ST	N	C	N	1"	2017	C	SF	Installation record	Y	2017	Visual insp during Field inspection only	Y	2017	Visual insp during install or repair
FALL RIVER COMMUNITY FIRE DIST	450-16 SOUTH ST	450-16 SOUTH ST	N	C	N	1"	2017	C	NONRES	Installation record	Y	2017	Visual insp during Installation record	Y	2023	Cross-connection survey
FALL RIVER COMMUNITY FIRE DIST	450-17 SOUTH ST	450-17 SOUTH ST	N	C	N	1"	2017	C	NONRES	Installation record	Y	2017	Visual insp during Installation record	Y	2023	Cross-connection survey
METALCRAFT OF MAYVILLE INC	200 STEEL RD	200 STEEL RD	N	DI	N				NONRES	Installation record	Y		Visual insp during Installation record	Y		
METALCRAFT OF MAYVILLE INC	200 STEEL RD	200 STEEL RD	N	DI	N				NONRES	Installation record	Y		Visual insp during Installation record	Y		
FALL RIVER POST OFFICE	203 STEEL RD	203 STEEL RD	N	C	N	1"			NONRES	Installation record	Y		Visual insp during Installation record	Y		
ESMILCO INC	209 STEEL RD	209 STEEL RD	N	C	N	1"			NONRES	Installation record	Y		Visual insp during Installation record	Y		
OELKE WAREHOUSE	642 STEEL RD	642 STEEL RD	N	C	N	1"			NONRES	Installation record	Y		Visual insp during Installation record	Y		
GOULD PLUMBING	680 STEEL RD	680 STEEL RD	N	C	N	1"			NONRES	Installation record	Y		Visual insp during Installation record	Y		
ORMMOSEN, PAULA	698 STEEL RD	698 STEEL RD	N	C	N	1"			SF	Installation record	Y		Visual insp during Installation record	Y		
BORDE, CHRISTOPHER & KATHRY	100 SUNRISE LN	100 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
YUDS, ERIC & ANGELA	102 SUNRISE LN	102 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
SMITH, BENJAMIN	105 SUNRISE LN	105 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
TRAMBURG, WYATT & CARISSA	112 SUNRISE LN	112 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
SCHULZE, GERALD	115 SUNRISE LN	115 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
FARR, THOMAS & PEGGY	120 SUNRISE LN	120 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
FRIEDLAND, CLAYTON & JODI	123 SUNRISE LN	123 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
GAYDOS, JOHN	128 SUNRISE LN	128 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
WAGNER, MALORY	131 SUNRISE LN	131 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
WEINBERGER, DAN	136 SUNRISE LN	136 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
KUEHL, TERRY	139 SUNRISE LN	139 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
MICKELSON, CRAIG	144 SUNRISE LN	144 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
DAUMAN, KELSEY	147 SUNRISE LN	147 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
YUDS, KELLY	152 SUNRISE LN	152 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
VOIGHT, JOHN & SARAH	155 SUNRISE LN	155 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
WALTER, KEVIN	160 SUNRISE LN	160 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
BROWN, DEREK	163 SUNRISE LN	163 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace rec	Y	2022	Visual insp during Field inspection only	Y	2022	Visual insp during install or repair
MACHKOVITZ, RHEA	168 SUNRISE LN	168 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
MOBRY, RYAN & OLIVIA	171 SUNRISE LN	171 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
STORMER, TIMOTHY & NICOLE	176 SUNRISE LN	176 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
FRISH, SUE	179 SUNRISE LN	179 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
PRIVETT, KELLY	201 SUNRISE LN	201 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
EDWARDS, IONATHON & AUBREY	202 SUNRISE LN	202 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
MAZZUCA, JOHN & KRYSYAL	203 SUNRISE LN	203 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
JOHNSON, ROBYN	204 SUNRISE LN	204 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
MILLER, MATTHEW	205 SUNRISE LN	205 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
DUNBAR, AMANDA	207 SUNRISE LN	207 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
HUEBNER, ANDY	209 SUNRISE LN	209 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
MITCHELL, SHEENA	211 SUNRISE LN	211 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
GRUCHOW, JUSTIN	213 SUNRISE LN	213 SUNRISE LN	N	C	N				MF	Installation record	Y		Visual insp during Installed after lead ban	Y		Visual insp during install or repair
BENNETT, CHRISTINE	215 SUNRISE LN	215 SUNRISE LN	N	C	N				MF	Installation record	Y		Visual insp during Installed after lead ban	Y		Visual insp during install or repair
BUBOLZ, SHANNON	217 SUNRISE LN	217 SUNRISE LN	N	C	N				MF	Installation record	Y		Visual insp during Installed after lead ban	Y		Visual insp during install or repair
JOHNSON, LINDA	219 SUNRISE LN	219 SUNRISE LN	N	C	N				MF	Installation record	Y		Visual insp during Installed after lead ban	Y		Visual insp during install or repair
LANDMARK INVESTMENTS	201-211 SUNRISE LN	201-211 SUNRISE LN	N	C	N				MF	Installation record	Y		Visual insp during Installed after lead ban	Y		Visual insp during install or repair
SCHUMANN PRINTERS	200 SWARTHOUT RD	200 SWARTHOUT RD	N	DI	N				NONRES	Installation record	Y		Visual insp during Field inspection only	Y		Visual insp during install or repair
SCHUMANN PRINTERS	200 SWARTHOUT RD	200 SWARTHOUT RD	N	DI	N				NONRES	Installation record	Y		Visual insp during Field inspection only	Y		Visual insp during install or repair
VITA BUILDERS LLC	235 SWARTHOUT RD	235 SWARTHOUT RD	N	C	N	1"	2000	C	NONRES	Installation record	Y	2000	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
SHEETMETAL SPECIALTIES IN	250 SWARTHOUT RD	250 SWARTHOUT RD	N	DI	N				NONRES	Installation record	Y		Visual insp during Field inspection only	Y		Visual insp during install or repair
DAUMAN ELECTRIC	295 SWARTHOUT RD	295 SWARTHOUT RD	N	C	N	1"	2000	C	NONRES	Installation record	Y	2000	Visual insp during Installed after lead ban	Y		Visual insp during install or repair
WB EQUIPMENT SALES INC	300 SWARTHOUT RD	300 SWARTHOUT RD	N	C	N				NONRES	Installation record	Y		Visual insp during Field inspection only	Y		Visual insp during install or repair
WB EQUIP BLDG #2	3008 SWARTHOUT F	3008 SWARTHOUT RD	N	C	N	1"	2019	C	NONRES	Installation record	Y	2019	Visual insp during Installed after lead ban	Y	2019	Visual insp during install or repair
SPURBECK, RON	105 TRANQUIL CT	105 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during Installed after lead ban	Y	2007	Visual insp during install or repair
LECLAIR, RYAN & USA	109 TRANQUIL CT	109 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during Installed after lead ban	Y	2007	Visual insp during install or repair
PEDERSON, CHAD	113 TRANQUIL CT	113 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during Installed after lead ban	Y	2007	Visual insp during install or repair
HUMPHREY, JASON	117 TRANQUIL CT	117 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during Installed after lead ban	Y	2007	Visual insp during install or repair
UNITED COOP	114 VITA PLUS DR	114 VITA PLUS DR	N	C	N				NONRES	Installation record	Y		Visual insp during Field inspection only	Y		Visual insp during install or repair
IDO FEED SUPPLY	638 VITA PLUS DR	638 VITA PLUS DR	N	C	N				NONRES	Installation record	Y		Visual insp during Field inspection only	Y		Visual insp during install or repair
VITA PLUS GRAIN	640 VITA PLUS DR	640 VITA PLUS DR	N	C	N				NONRES	Installation record	Y		Visual insp during Field inspection only	Y		Visual insp during install or repair